

Assembly Alert: 116

Date: December 5, 1994

Subject: Wing Rib Compression Tube Length

Compliance: Mandatory

Models Effected: S-7 Courier From 12/93 to 12/94

In your S-7 Courier Assembly Manual, page 011-11, Figure 011-023 has a typing error. The wing rib AFT compression tube length should be corrected as follows:

was 5 3/4" is 5 3/8"

Please check your manual and make corrections accordingly or replace your existing page with the corrected page provided with this alert.

