

# RANS

4600 Highway 183 Alternate  
Hays, KS 67601  
(785) 625-6346  
Fax (785) 625-2795  
www.rans.com

**Assembly Alert: 178**

**Date: December 23, 2015**

**Subject: Seat Bottom Cushion sewn without Lacing Wire Pocket**

**Compliance: Mandatory**

**Models Affected: S-6ES, S-6S and S-20**  
**(shipped from June 2015 thru December 2015)**

You may have received Seat Bottom Cushions (ST-SBTC-A) that have been sewn minus the pocket for the lacing wire. The photos below show the difference. Please inspect your cushions. If your cushions are without the small pocket, please return them for correction. We will add the pocket and return the cushions as promptly as possible.



Thank you for your attention to this matter. RANS hopes that we have not inconvenienced you to any great degree. Fly safe!