



4600 Highway 183 Alternate
Hays, KS 67601
(785) 625-6346
Fax (785) 625-2795

Operational Alert: 156

Date: December 13, 2001

Subject: Inspect IVO 3-Blade Propeller on 3:1 Gear Box

Compliance: Mandatory

Models Effected: All S-18 With 3:1 Gear Box

If operating with IVO 3-blade quick adjust propeller on 3:1 gearbox on 503 or 582 engine, please inspect propeller frequently as per IVO Propeller service bulletin number 2.

Failure to do so may cause propeller to loosen and separate from aircraft.

Thank you for your attention to this matter. Hopefully we have not inconvenienced you to any great degree. Fly safe!