

# RANS

4600 Highway 183 Alternate  
Hays, KS 67601  
(785) 625-6346  
Fax (785) 625-2795

**Assembly Alert: 167**

**Date: June 19, 2009**

**Subject: Incorrect GAP-2 Gap seal**

**Compliance: Mandatory**


**Models Affected: S-6S, S-7, S-7S, S-9, S-10 shipped August, 2008 thru May, 2009.**

It has come to our attention that Gap Seal (RANS# GAP-2) were incorrectly made by the manufacturer.


Please compare the GAP-2 you received with your kit to the template below.

If your GAP-2 does not match the template below contact Dennis at Central Plastics (620-241-5800) for replacement parts.

CORRECT



INCORRECT



MD4915

Thank you for your attention to this matter. I hope that we have not inconvenienced you to any great degree. Fly safe!