

**AIRWORTHINESS DIRECTIVE: 104**

**DATE: 2/22/93**

**SUBJECT: AFT STRUT MATERIAL**

**COMPLIANCE: MANDATORY**

**MODELS EFFECTED: S-9 CHAOS AND S-10 SAKOTA**

It has been determined that the Aft Strut Material supplied with your kit is possibly 12% deficient in strength. This is due to unauthorized changes made in the profile and thickness by the extruder. Enclosed is a sample of what your strut material should be like. Please use this as a comparison tool to your strut. If your strut does not match exactly in shape and thickness, please make arrangements to return your two aft lift struts for replacements.