



AIRWORTHINESS DIRECTIVE: #116

DATE: DECEMBER 30, 1998

SUBJECT: S-12 912 MUFFLER INSPECTION

COMPLIANCE: MANDATORY

MODELS EFFECTED: ALL S-12 912 MUFFLERS  
+ S-12XL

Internal reinforcements in the muffler canister may separate and enter the exhaust manifolds and contact the exhaust valves, causing extensive damage to the engine. Remove and inspect all 912 muffler canisters by shaking. Loose reinforcements will be apparent by the noise. If loose reinforcements are present, replace canister with new unit.