



***Airworthiness Directive:*** 120

***Date:*** January 22, 2001

***Subject:*** Elevator Yoke Exit

***Compliance:*** Manditory

***Models Effected:*** S-6S & S-6SXL Coyote II

**NOTE:** Applies to "curved" longeron tail cones ONLY.

Please use the enclosed information to verify that your elevator yoke exit is in the correct location.

Thank you for your attention to this matter. Hopefully we have not inconvenienced you to any great degree. Fly safe!

FIGURE 017-07 (continued)

MD3490

